Athens Gas Light and Electric Company Building (Athens Lumber Company)
Factory Street west of the Athens Railroad Station
Athens
Athens County
Ohio

HABS No. OH-692-A

HAVE CX110, 5-ACH,

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS OHIO 5-ATH, 4A-

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY		
Ohio	Athens		Athens	Athens	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
Athens Gas Light and Electric Company Building				ОН-692-А	
SECONDARY OR COMMON NAMES OF STRUCTURE					
Athens Lumber Company					
COMPLETE AODRESS (DESCRIBE LOCATION FOR RURAL SITES)					
Factory Street west of the Athens Railroad Station U.T.M. coordinates 17.404500.4353590					
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)					
1878 (Athens County deeds and records) Unknown					
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Athens Gas Light and Electric Company was one of the earliest industrial enterprises that developed in the area southwest of the Athens railroad station in the mid-nineteenth century. This structure later became part of the Athens Lumber Company which did much of the millwork for Ohio University when it was built.					
STYLE (IF APPROPRIATE)					
MATERIAL OF CONSTRUCTION (INCLUOE STRUCTURAL SYSTEMS)					
Load-bearing brick, frame shed built onto east end					
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
Rectangular					
EXTERIOR FEATURES OF NOTE One-story brick structure, gable roof, segmentally arched door openings					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Brickwork around large windows on facade has been repaired, changing segmentally arched opening to rectangular opening; shed attached to east end.					
PRESENT CONDITION AND USE					
Fair condition; being used as lumber shed					
OTHER INFORMATION AS APPROPRIATE					
· · · · · · · · · · · · · · · · · · ·				,	
SOURCESOF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Ohio Historic Inventory					
COMPILER, AFFILIATION			DA	TE	
Myra Moss-Horvath, AThens C	ity-County Deve	elopment Board	į	February 1982	